



State of Utah  
DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt  
Governor


Kathleen Clarke  
Executive Director

Lowell P. Braxton  
Division Director

1594 West North Temple, Suite 1210  
PO Box 145801  
Salt Lake City, Utah 84114-5801  
801-538-5340  
801-359-3940 (Fax)  
801-538-7223 (TDD)

August 27, 1999

TO: Minerals File

FROM: Lynn Kunzler, Senior Reclamation Specialist 

RE: Site Inspection, Bear Lake State Park, Garden City Quarry, S/033/003, Rich County, Utah

Date of Inspection: August 25, 1999  
Time of Inspection: 7:00 a.m.  
Conditions: Clear and Warm  
Participants: Lynn Kunzler, DOGM

Purpose of Inspection: To evaluate site conditions.

The annual report submitted for this site indicated that 7 acres had been disturbed by mining activities. Phone conversation with Eldon Robinson of Bear Lake State Park indicated that the acreage may be in error. A GPS unit was used to determine the acreage of current disturbance.

The site did not appear to have change much since the last inspection with estimated acreage of about 4 acres. The one notable change is a section in the northeast corner of the site has been reclaimed. A phone call to Eldon Robinson after the inspection indicated that John Blake of SITLA had requested that the reclaimed area needed to be reseeded because of the large number of weeds on this area. This will be done this fall. Also, it appears that local recreationists use this site for riding their ATV's. No other problems were apparent at the site.

Results of the GPS survey show a total of 3.82 acres of disturbance. This includes the .99 acres that were reclaimed. A copy of the GPS survey will be sent to the Bear Lake State Park. UTM coordinates for the site as determined with the GPS is North 4643977, East 465982.

Several photos were taken at this site.

jb  
cc: Eldon Robinson, Bear Lake State Park w/GPS survey  
S33\_03.ins